



Use two pencils and a ruler to measure the distances. Unless you have access to Calipers.




**Cheek: Side padding**

Measure highest point on the cheek bones about 1.25" in front of ear.




**Jaw: Side padding**

Measure about where the jaw hinges. Directly below where the cheek measurement was taken.




**Front to Back: Mask depth**

Measure from the center of the forehead to the back of the head.




**Top of head to eyes: Cage placement**

Measure from the center of the eyes to the top of the head.



**Side to Side 1: crown padding**  
Measure side to side about 1"  
above the middle of the ears.



**Side to Side 2:**  
Measure top of the temple to top  
of the temple.